DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453

(707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-021130 Address: 333 Burma Road **Date Inspected:** 09-Oct-2010

City: Oakland, CA 94607

Project Name: SAS Superstructure **OSM Arrival Time:** 700 **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Xu Xian Ping No Yes N/A **Rod Oven in Use:** Yes **Inspected CWI report:** No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component: OBG** Segment Assembly

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Ramesh Gade, was present during the times noted above for observations relative to the work being performed.

Bay 6/CB 18

This QA Inspector observed the following work in progress:

Flux Core Arc Welding (FCAW) in the 3G position of weld joint CB3002J-001-045 located on CB 18. The welder is identified as 053609. ZPMC CWI is identified as Zheng Zhi Wei. The welding variables recorded by QC appeared to comply with the WPS B-T-2233-TC-U5-F. See attached photograph Pic_001.

Bay 7 /Steel Barrier W2-SB9

This QA Inspector observed the following work in progress:

Flux Core Arc Welding (FCAW) in the 2F position of weld joint W2-SB9-001-024 located on Steel Barrier W2-SB9. The welder is identified as 066163. ZPMC CWI is identified as Xu Hai Yang. The welding variables recorded by QC appeared to comply with the WPS B-T-2132-3.

Bay 7/OBG Segment 14W

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA Inspector observed the following work in progress:

Flux Core Arc Welding (FCAW) in the 2F position of weld joint DP3184-001-001 located on Deck Panel plate DP3480A to 'I' rib. The welder is identified as 204342. ZPMC CWI is identified as Xu Hai Yang. The welding variables recorded by QC appeared to comply with the WPS B-T-4132. See attached photograph Pic_002.

Bay 8/OBG Bike Path

This QA inspector performed Magnetic Particle Testing (MT) approximately 15% of the area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated MT report for this date. The member is identified as Steel Barriers as per ZPMC notification # 06901 items # 1, 5, 6, 7 and 8.

The weld designations reviewed are as follows:

Item # 1 BK004A6-055-055, 056, 059, 060, 104, 105, 106, 107, 108 and 109

Item # 2 BK004A6-055-013, 015, 016, 019, 020, 021, 031, 032, 029, 030, 041 and 042

Item # 3 BK004A6-055-117, 118, 033, 034, 043, 162, 045, 046, 047, 048, 049 and 163

Item # 4 BK004A8-055-013, 015, 016, 019, 020, 021, 022, 115, 116, 031, 032, 029, 030, 041 and 042

Item # 5 BK004A8-055-033, 034, 117, 118, 043, 044, 045, 046, 047, 048, 049, 050,055, 056, 059,

060, 104, 105, 106, 107, 108 and 109





Summary of Conversations:

No relevant conversations reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (+86)15000 42 2372, who represents the Office of Structural Materials for your project.

Inspected By: Gade, Ramesh Quality Assurance Inspector

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Reviewed By: McClendon, Timothy QA Reviewer